



In re Patent Application of:

Yong-deok CHANG et al.

Application No.: 10/625,614

,

Confirmation No.: 7911

CERTIFICATE OF CORRECTION

Filed: July 24, 2003

BRANCH

ATTENTION

U.S. Patent No.: 7, 218,673

Issued: May 15, 2007

For: CHANNEL EQUALIZER OF SINGLE CARRIER RECEIVER AND EQUALIZING

METHOD THEREOF

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistakes shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date:

By:

Gene M. Garner, II

Registration No. 34,172

Certificate

AUG 0 1 2007

of Correction

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500

Facsimile: (202) 434-1501

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7, 218,673

DATED: May 15, 2007

INVENTOR(S): Yong-deok CHANG et al.

Column 8, Line 44, after "ratio" insert --(SNR)--.

Column 8, Line 47, change "comprises;" to --comprises:--.

Column 9, Line 58, change "eciualizer" to --equalizer--.

Column 9, Line 61, change "signal:" to --signal;--.

Column 9, Line 63, change "signal:" to --signal;--.

Column 9, Line 65, change "symbols:" to --symbols; --.

Column 10, Line 28, change "Natural" to -- National -- .

Column 12, Line 8, change "L:" to --L;--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP 1201 New York Ave., N.W. 7th Floor Washington, DC 20005 PATENT NO. 7, 218,673

No. of add'l copies @ 50¢ per page

